
FEI Helios NanoLab 460F1 FIB operational guide AggieFab Texas A&M University







Department of Electrica

Contents

- Start up the Helios
- Stages load/unload
- Electron/Ion beam control for SEM / FIB users
- Turning on E-beam & I-beam
- Toolbars icons/menus
- Eucentric height
- E-beam alignment
- FIB procedure
- Patterning tap
- TEM lift-out grid
- TEM sample holder
- Lamella lift-out procedure: Cap deposition, Trenches, Easy-lift procedure,

ĀМ

 $\operatorname{TEXAS}_{U \ N \ I \ V \ E \ R \ S \ I \ T \ Y} M$

Texas A&M Engineering Experiment Station

Finishing the secession

□ SCOPE

• The purpose of this document is to describe requirements and basic operating instructions for the FEI Helios SEM/FIB System. The use of this tool is limited to approved processes only.

□ SAFETY

- Be sure that you are trained and signed off to use this equipment.
- Be sure to keep all doors and protective shields in place before operating this equipment.
- Use care when operating around high voltage or high current.
- If you are unsure about any procedure or indication while operating this equipment be sure to contact a staff member or trainer for assistance.

Texas A&M Engineering Experiment Station

 $\begin{array}{c} TEXAS A \& M \\ U & V & F & S & I & T \\ \end{array}$

Beginning your session

Note:

- Always check the stage in quad 4 on the screen when loading/unloading your samples.
- Please contact staff for ferromagnetic powers/particles or small samples.
- For ferromagnetic samples, place your sample securely on the stub so that samples will not hit the objective lens.

Starting your session

- 1. Start iLab.
- 2. Log in to the user software
- 3. Load your sample
 - 1. Check the height of your sample (pictures on next slide)
 - 2. Load samples (next slide)
 - 3. Wait until the stage transfers to the loading/unloading chamber
 - 4. Release the stage: 'Release' button
 - 5. Pick up the stage, load your sample, and place the stage back on the stage holder
 - 6. Click 'Load' button
 - 7. Wait until the stage transfer is completed
- 4. Take a Navigation picture
 - 1. In the menu, 'stage' 'take nav-Cam Photo'
 - 2. Explore the sample locations by clicking the specific locations in the picture at 3rd quad

ĀМ

TEXAS A&M


ſĨŦŦ

Texas A&M Engineering Experiment Station

Sample mount and loading/unloading

Sample stage: five slots





Unloading Sequence

- 1. Push the Unload / Release button to start the unloading sequence (lit is blinking). After finishing, the Loadlock is vented and the lid can be opened. Both buttons are enabled.
- 2. Open the lid, the Clamp / Load button becomes disabled. Push the Unload / Release button to release the carrier from the Loadlock arm.
- 3. Take the carrier out from the Loadlock arm.


Loading Sequence

 $\operatorname{TEXAS}_{U N I V E R S I T Y}_{U N I V E$

ĀМ

1. Place the carrier on the Loadlock arm, making sure that all three alignment rubies are positioned properly. The Clamp / Load button becomes enabled (lit is on).

Figure 5-7 Alignment Rubies with Only Two Shown




2. Close the lid and push the Clamp / Load button. The loading sequence starts (lit is blinking).

Texas A&M Engineering

Experiment Station

Department of Electrical

& Computer Engineering



| Ion beam heater <mark>OFF</mark> state Never click the Wake Up button Sleep button should be grayed out. | | |
|--|--------------|--|
| System | ? | |
| Wake Up | Sleep | |
| Column | ? 😽 | |
| | Beam Current | |

~

Beam On

High Voltage

↔ 🗸

80 pA - +

+

30.00 kV -

Ion beam <mark>ON</mark> state If you see the Sleep button is activated, please click it to deactivate it

| System | ? |
|----------------------------------|--------------|
| Wake Up | Sleep |
| Column | ? 🍪 |
| Beam On | Beam Current |
| High Voltage ↔ <mark>↓</mark> | 30.00 kV -+ |
| Magnification | ? 🍪 |

TEXAS A&M UNIVERSITY

Department of Electrical & Computer Engineering

ĀМ



FIB USERS

Not operating state: FIB not using \rightarrow Ga ion source heater off → Ga ion beam not scanning System ? Wake Up Sleep ? 🏀 Column Beam Current ¥ 80 pA - + Beam On High Voltage ↔ 🗸 30.00 kV - +

Heater on by click Wake Up → start to consume ion source → Ion beam yet to start to scan

| System | ? | |
|------------------------------|--------------|--|
| Wake Up | Sleep | |
| Column | ? 🏀 | |
| (Beam On High Voltage | Beam Current | |
| ↔ ✓ | 30.00 kV -+ | |
| Magnification | ? 🏀 | |
| Counte Magnifications | | |

Ga+ source completely heated up - operational Ion beam scan by click Beam On Good to go for FIB

> Texas A&M Engineering Experiment Station

TEXAS A&M UNIVERSI

Department of Electrical & Computer Engineering

A M

| System | ? |
|---------------|--------------------------|
| Wake Up | Sleep |
| Column | ? 🏀 |
| Beam On | eam Current 80 pA - + |
| High Voltage | |
| ↔ • | 30.00 kV -+ |
| Magnification | ? 🏀 |

| When FIB is finished, |
|-----------------------|
| |
| 1) Click 'Sleep' |
| 2) Click 'Beam On' |

| System | ? | |
|--------------|--------------------------|--------------------------|
| Wake Up | Sleep | Sleep button deactivated |
| Column | ? 🏀 | |
| Beam On | Beam Current 80 pA -+ | |
| High Voltage | 30.00 kV -+ | |


TM | TEXAS A&M.

Pages Toolbar

Ion Beam Current:

😽 🚡 🧎

41



Turning e-beam

TEXAS A&M UNIVERSITY.

A M

- 1. Click 'Beam control' in the Pages Toolbar
- 2. Click 1st quad on the monitor screen
- 3. Select the voltage and current
 - Menu bar or
 - <u>'Beam Control page'</u>

| ſŦĨŦŦ

- 4. Click the <u>Beam on</u> button under the <u>'Beam</u> <u>Control page'</u> tab
- 5. Unpause the screen using the 'Pause' icon

Texas A&M Engineering

Experiment Station

Department of Electrical

& Computer Engineering

Start Ion beam (FIB users)


Pages Toolbar

41

5 008-6 mba

Chamber Pressure

😽 🚡 🌶



Turning lon-beam

 $\operatorname{TEXAS}_{U \ N \ I \ V \ E \ R} A \overset{\bullet}{A} \overset{\bullet}{M}_{I \ V}$

[ĨŢŢ

A M

- 1. Click the 2nd quad on the screen
- Click the 'Wake Up' button (arrow)
- 3. Click the 'Beam On' button (arrow)
- Leave the ion-beam as paused
 - The green pause symbol is shown *left top screen*

Texas A&M Engineering

Experiment Station


TEXAS A&M UNIVERSIT

Department of Electrical


& Computer Engineering

Toolbar icons/menus

Toolbar Left Half



Toolbar Right Half



TEXAS A&M UNIVERSITY

Department of Electrical

& Computer Engineering

М

Texas A&M Engineering

Experiment Station

TEXAS A&M

111777

ĀМ


Eucentric height for FIB users

- 1. Link Z to working distance
 - Focus on the sample surface with SEM
 - Click 'Z to WD' icon: the icon changes its shape with green arrow.
- 2. Set the working distance to 4 mm.
 - Input 4 in the Z (Navigate page)
 - Click 'go to' button
- 3. Find Eucentric height/point: the height of the stage where the specific point remains the same at tilt = 0 and 52
 - Set magnification X1000
 - Find a recognizable feature, and center it under the yellow cross by moving the stage
 - Watching the feature, change the stage tilt to 10°. Using the Z control, bring the feature back under the cross
 - Repeat the previous step at 20° or 30°
 - Repeat at tilt = 52°

'Z to WD icon'

- Red question mark: The function is enabled and the link between Z and FWD is unknown. Use the function as soon as possible, after properly focusing the image.
- **Red circle**: The function is enabled. Z is roughly linked to FWD, but it needs correction. This could happen after changing the sample, focusing and linking Z to FWD at a long working distance (WD), and then moving the stage to a short WD. Focus the image carefully at a WD around 4 mm and use this function again.
- Green double-ended arrow: The function is still enabled and Z is properly linked to FWD. It is now safe to change the WD hy setting a 7 coordinate on the Stage nage

Stage move up/down



Department of Electrica

& Computer Eng

Texas A&M Engineering


Experiment Station

'Nevigate'

Bulk Flip Tilt Correction EasyLift

- 1. Focus on the surface with the magnification you will be doing operation.
- 2. Adjust stigma
- 3. Do the lens modulation
 - 1. Click 'Direct Adjustments' icon
 - 2. Click 'Crossover' button and center the beam
 - 3. Click 'HV Modulator' and make the image static by adjusting the horizontal and vertical lines. Click and drag the lines one by one.
- 4. Adjust focus and stigma again.

'Direct Adjustments'



Texas A&M Engineering

Experiment Station

Department of Electrica

& Computer Engineering

TEXAS A&M

TÉÈ∓-

ĀМ

For SEM USERS

do your job and move to the last slide to shutdown the system

For FIB USERS


Go to next slide





Starting Ion-beam, tilt = 52°

- 1. Click 2nd quad on the screen
- 2. The Ga ion source was activated previously by clicking the 'Wake Up' button.
- 3. Select the '<u>Beam Current</u>' and '<u>High Voltage</u>': those can be selected in the 'Beam control page' or in the menu bar.
- 4. Before scanning I-beam, adjust the magnification.
- 5. Once the 2nd quad is unpaused, the ion beam scans the sample area.
- 6. 'Shift' key + 'mouse left drag' is used to shift the I-beam image to align it with the SEM image.
- 7. Adjust focus and stigma



| Aper | ture | use |
|------|------|---|
| 1.1 | pА | High resolution imaging |
| 7.7 | pА | High resolution imaging |
| 24 | pА | High resolution imaging, small cross section cleaning |
| 40 | pА | General resolution imaging, cross section cleaning |
| 80 | pА | General resolution imaging, cross section cleaning |
| 230 | pА | Imaging, cross-section cleaning |
| 430 | pА | Cross-section cleaning |
| 790 | pА | Medium bulk milling or large cross-section cleaning |
| 2.5 | nA | Large cross-section cleaning |
| 9.3 | nA | Rough bulk milling for large cross-sections |
| 21 | nA | Extremely rough bulk milling for large cross-sections |
| 47 | nA | Extremely rough bulk milling for large cross-sections |
| 65 | nA | Extremely rough bulk milling for large cross-sections |

Texas A&M Engineering

Experiment Station

Department of Electrica

& Computer Engineering

A M

 $\operatorname{TEXAS}_{U \ N \ I \ V \ E \ R \ S \ I \ T \ Y_{*}} M$

1. Select a pattern from the Pattern Selector and draw a pattern in the active quad (1st quad: electrons, 2nd quad: ions).




- 2. Select a beam for patterning from the toolbar.
- 3. Enter a value in µm as the depth in the Property Editor.
- 4. Select the milling aperture.
- 5. Focus and stigmate the beam on the area adjacent to the pattern.
- 6. Snapshot a single frame to confirm the pattern position.
- 8. Select Patterning > Start Patterning or click Start Patterning on the toolbar to begin milling.
- 9. Pause, resume, and stop patterning by clicking the corresponding buttons in the menu bar



Department of Electrica

& Computer Engineerin

ĀМ



Patterning Properties

| Basic | Advance | d Progress S. Mill |
|--------------|---------|--------------------|
| Name | | Value |
| Applica | ation | |
| Xisize | | 0 μm |
| Y size | | 0 μm |
| Z size | | 0 μm |
| ScanDi | rection | Bottom To Top |
| DwellTi | ime | 0 s |
| Beam | | Electron |
| Time | | 0 s |
| Beam Current | | 0 pA |

ĀМ


Application: Name of the application. Clicking the value field produces a dropdown arrow and list of applications. The parameters for the selected application are automatically set for the subsequent properties. **Scan Direction:** Bottom to Top or Top to Bottom, etc. **Beam:** The beam used for patterning **Beam Current:** The amount of current striking the sample.

Department of Electrical


& Computer Engineering

TEM lift out grid


Placing TEM grid holder on the base



Clamping the grid



Releasing the holder



Texas A&M Engineering Experiment Station

AM


Department of Electrical & Computer Engineering


TEXAS A&M

ĀМ

TEM sample holder

Dedicated stage for the TEM grid holder





TEXAS A&M. TEES

TEXAS A&M UNIVERSIT


Department of Electrical & Computer Engineering


Texas A&M Engineering Experiment Station

TEM sample lift out flow

1. Cap deposition2. trenches3. J cutPt/Cfilt = 0Tilt = 0


4. EasyLift: micromanipulator for sample handling





ĀМ

Cap deposition



TEXAS A&M UNIVERSITY

Department of Electrical

& Computer Engineering

ĀМ

Texas A&M Engineering

Experiment Station

TEXAS A&M

ĀМ


- 1. Deposition for protecting the sample. Example: carbon and Pt deposition
 - 1. E-beam induced deposition, stage tilt = 0°
 - 1. In the 'Pattern' tab, draw a rectangle pattern in the 1st squd (SEM)
 - 2. In the 'Application', select 'C e-dep surface'
 - 3. Insert gas injector needle: click the square for the gas you want to use
 - 4. Hit the start icon, triangle in the menu
 - 5. Low HV (<5kV) and high current (~26nA)
 - 6. Retract the gas nozzle
 - 2. I-beam induced deposition, stage tile = 52°
 - 1. Align the SEM and the FIB images using 'beam shift'
 - 2. Click the 2nd sqad, and draw the pattern on the pattern
 - 3. Ex) carbon & Pt deposition, carbon deposition 'C_M' and followed by Pt, 'Pt_dep'

Texas A&M Engineering Experiment Station

TEXAS A&M

- 1. Ion beam current depends on the size of patterns.
- 2. Check focus, stigma, and shift when the beam current changes

Trenches



ĀМ

Experiment Station

Department of Electrical

& Computer Engineering

Trenches


- 1. Cross-section cuts 'Regular Cross Section 1' top and bottom of the protection pattern
 - 1. Draw the cut patterns that are a couple microns wider than the protection pattern
 - 2. For bulk cuts, high current might be chosen. Adjust focus and stigma.
 - 1. Turn off the beam blaker, full screen, and then check the beam using the snapshot
 - 1. 'Scan' 'Spot' mode. Select the point where the beam is pointing at.
 - 2. 'Scan' 'Beam Blank'. I-beam exposure immediately.
 - 3. 'Scan' 'Full Frame'.
 - 2. Put the gaps between the cut and the protection pattern according to the beam size

Texas A&M Engineering Experiment Station

TEXAS A&M

- 2. Cleaning cross section cut with two or three lower aperture (~20nA or less if needed)
 - 1. Application 'Si New'`

Easy-Lift: micromanipulator



ĀМ


Department of Electrical

& Computer Engineering

Experiment Station

TEM sample lift out

5. Lift out the sample



TEXAS A&M UNIVERSITY

Department of Electrical

& Computer Engineering

ĀМ


Texas A&M Engineering

Experiment Station

TEXAS A&M

Ā M

TEM sample lift out - continued



TEXAS A&M UNIVERSITY


Department of Electrical

& Computer Engineering

ĀМ

*|[*4]∓7

Place the sample on the grid



TEXAS A&M UNIVERSITY

Department of Electrical

& Computer Engineering

Texas A&M Engineering


Experiment Station

TEXAS A&M

ĀМ

Shutdown the system: FIB session

If you used the micromanipulator, Retract the micromanipulator



Finish the secession

- 1. Click the 'Pause' button to stop beams
- 2. Tun off the lon-beam:
 - Click 2nd quad
 - Click '<u>Beam On</u>' AND '<u>Sleep</u>' button
- 3. Tun off the Electron-beam:
 - Click 1st quad
 - Click 'Beam On'
- 4. Set tilt = 0
- 5. Unload your samples
- 6. Transfer the stage back to the main chamber:

 $\operatorname{TEXAS}_{U N I V E R S I T Y}^{W}$

• wait until the stage comes back to the main chamber

Texas A&M Engineering Experiment Station

Department of Electrical & Computer Engineering

- Check visually through the CCD CAM at quad 4.
- 7. Log off the SEM/FIB software

ĂМ

- File log off
- 8. Log off iLab

Finish the secession

ĂМ

TEXAS A&M

[ĴĴŢ]

Texas A&M Engineering Experiment Station

Department of Electrica

- 1. Click the 'Pause' button to stop beams
- 2. Tun off the Electron-beam:
 - Click 1st quad
 - Click 'Beam On'
- 3. Set tilt = 0
- 4. Unload your samples
- 5. Transfer the stage back to the main chamber:
 - wait until the stage comes back to the main chamber
 - Check visually through the CCD CAM at quad 4.
- 6. Log off the SEM/FIB software
 - File log off
- 7. Log off iLab

SIGNATURES AND REVISION HISTORY

- 1. Original author of this document: Dr. Sung Oh Woo
- 2. Original author Title or Role: Research Engineer
- 3. Date of original: 9/1/2022
- 4. Revision B notes: description of the LMIS handling is added

Approvals:

Technical Manager Signature: ____Sandra G Malhotra

Date: ___6/7/2024__

| Revision | Author | Date |
|----------------|-------------|----------|
| Original Issue | Sung Oh Woo | 9/1/2022 |
| Rev B | Sung Oh Woo | 6/7/2024 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

AggieFab Nanofabrication Facility



ĀМ